
















ARMOIRE VINTAGE METAL


nordic • factory



A	X4	B	X4	C	X6	D	X4	E	X2
									
M6x40		M3x8		M5x12					
F	X4	G	X4	H	X4	I	X4	J	X2
									
						M3			
K	X4	L	X4						
									
M5x12		M5							




1




⊕ 
CX3


2




3




4



5




6



A x 4

7




G x 4




C x 12

8




C x 6

9



C x 16

10




D x 4




C x 12


11




C x 10

12










14











15



16



 J x 2	 E x 2	 H x 4	 F x 4
 B x 4	 I x 4	 K x 4	 L x 4

17

